


# Skid Bars



## Skid Bar, laminated wear parts 700 HB

ProMite skid bars are easy to use and install. No pre or post heating needed when welding.

ProMite skid bars can effectively be used on a variety of buckets, loader, excavator or drag line buckets. The ProMite skid bars are perfect for corners, edges and hard to reach places. Use ProMite skid bars wherever you need impact and wear resistance.

Part No.	Dimensions					Weight Kg
	A mm	B mm	C mm	D mm	E mm	
PM412SB	250	150	20	25	45	13,1
PM413SB	200	150	20	25	45	10,5
PM414SB	250	250	20	25	45	21,9
PM416SB	250	200	35	15	50	20,0